

Report تويوتا PRADO 2022

Report Date 2026-10-01

*Information Below is based on Report Date

موجز
Mojaz

Report No.: 14788542

Plate No.: R S S 4506

Sequence 591228220

VIN: JTEBU3FJ3NK224868



Scan the QR code to view the digital

Vehicle Information

Vehicle Model	PRADO	Plate Number	R S S 4506
Vehicle Maker	تويوتا	Color	Dark brown
Year	2022	Vehicle Weight	2115
VIN	JTEBU3FJ3NK224868	No. Passengers	7
Seq	591228220	Chassis Type	9 passengers or less

Report Summary



Highest Odometer

96724 km



No. Vehicle Owners

2

*Including the current



Accident Images

Available



Accidents Number

1



Agency Records

No maintenance



Assessed as a total loss?

No

*Damage Assessment



Periodic Inspection

Valid



Number of

1



The report was issued based on data
available as of 2026-10-01
Scan QR code for Terms and Conditions



Vehicle Ownership

Current Owner

Vehicle Purchase Date
2026-03-26

Ownership Duration
6 months

Owner #1


Vehicle Purchase Date
2026-03-17

Ownership Duration
Less than a month



Technical Vehicle Specification

Maker	TOYOTA	Model	LAND CRUISER PRADO
Vehicle Trim	VXR	Engine size	4.0 L
Fuel type	Petrol	Body type	SUV
Number of Cylinders	6	Transmission type	AUTOMATIC
Driving type	4WD		






Vehicle Record

No. Authorizations	1	No. Owners	2
No. of Periodic	1	Result of Last Inspection	ناجحة
Expiry date of inspection	2027-03-17	Vehicle Registration	Private
Registration issue date	2026-03-17	Registration expiry date	2029-02-12

Odometer Readings History


Source	Reading	Reading Date
Periodic Inspection (MVPI)	96724 km	2026-03-17






 Accident Records

Accident 1

Accident Date	2026-07-05	Accident City	مدينة جدة
Accident	Collided with a moving vehicle	Accident Severity	Not Available
Damage Place	Not Available		
Accident Images			
			

 Damage Assessments and Images

The vehicle has not been assessed by accredited centers





Vehicle Repair Data



Ertah is Platform that refer to retrieve all repair details that happened by workshops

Repair 1


Workshop Name	اديشن موتورز	Workshop Location	عسفان
Fix Permit ID	2608155373	Repair Type	Accident
Damage	Not Available	Repair Details	Not Available
Check-in Date	2026-08-15	Check-in Time	05:59 PM
Check-out Date	2026-09-10	Check-out Time	11:50 PM



Vehicle Repair Images

Fix Permit ID: 2608155373

Vehicle Images at Check-in



The report was issued based on data available as of 2026-10-01
Scan QR code for Terms and Conditions

